Nevins Log House

Thurmont vicinity

Private

The Nevins Log House is located at the intersection of Eyler's Valley Flint Road and Debold Road several miles northwest of Thurmont, Maryland. The principal elevation faces north with a gable roof on a east-west axis. The property includes a large stone springhouse, a bank barn with an attached drive-through shed and a chicken coop. The house is important in showing an original log dwelling house that has been changed to accommodate late twentieth century ideas. These changes have altered the appearance, form and type of building that the nineteenth century owners intended. The outbuildings that accompany the house, no longer in use, exemplify buildings of a mountain farm.

F-6-84 Nevins Log House Thurmont, Maryland Frederick County

HISTORIC CONTEXT:

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA

Geographic Organization: Piedmont (Harford, Baltimore, Carroll, Frederick, Howard, Montgomery Counties, and Baltimore City)

Chronological/Development Period:
Agricultural-Industrial Transition 1815-1870 A.D.
Industrial/Urban Dominance 1870-1930 A.D.

Prehistoric/Historic Period Themes:
Architecture, Landscape Architecture and Community Planning
Agriculture

Resource Type:
Category: Buildings

Historic Environment: Mountains

Historic Function and Use:
 Domestic/single dwelling/residence
 Domestic/secondary structure/springhouse
 Agricultural/Subsistence/agricultural outbuilding/barn, chicken coop

Known Design Source: None

MARYLAND INVENTORY OF Maryland Historical Trust HISTORIC PROPERTIES State Historic Sites Inventory Form

Survey No. F-6-84

Magi No.

DOE __yes __no

4 11				
1. Nam	e (indicate pr	referred name)		
historic Nevi	ns Log House			
and/or common				
2. Loca	ation			
street & number	6994 Eylers Va	lley Flint Road		_ not for publication
city, town Th	urmont	_X vicinity of	congressional district	6th
state Ma	ryland	county	Frederick	
3. Clas	sification			
Category districtX building(s) structure site object	Ownership public private both Public Acquisition in process being considered not_applicable	Status _X occupied unoccupied work in progress Accessible _X yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names an	d mailing addresses	of <u>all</u> owners)
name Jane	F. Nevins			
street & number	560 N Street, S.	W., Apt. 8910	telephone no	·:
city, town Wa	shington D.C.	state	and zip code 2	0024
5. Loca	ation of Leg	al Descriptio	n	
courthouse, regis	stry of deeds, etc. Fre	derick County Courth	ouse	liber 1555
street & number	100 W. Patrick	Street		folio 634
city, town	Frederick		state	Maryland 21701
6. Repr	esentation	in Existing	Historical Surve	eys
title				
date			federal state	county loca
depository for su	rvey records			
city, town			state	

Condition		Check one	Check one	
excellent	deteriorated	unaltered	X original site	
_X good	ruins	X altered	moved date of move	e
fair	unexposed			

Survey No.

F-6-84

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

(Typed on separate sheet)

7. Description

8. S	ign	ificance		Survey No.	F-6-84
	⊢1499 ⊢1599 ⊢1699 ⊢1799 ⊢1899	_X architecture art commerce	community planning	law literature military music mphilosophy	religion science sculpture social/ humanitarian theater hent transportation other (specify)
Specific	dates	-	Builder/Architect		
check:	ar Appli	cable Criteria:A ad/or cable Exception:A of Significance:	A _B _C _D _1		
Prepare support		a summary paragraph o	of significance and a	a general statem	ent of history and
(Typed	on se	eparate sheet)			

I

9. Major Bibliographical References

Survey No. F-6-84

Atlas of Frederick County, Maryland, C.O. Titus and Co., Philadelphia, 1873.

Map of Frederick County, Maryland, Isaac Bond, Baltimore, 1858.

10. Geographical Data		
Acreage of nominated property 26.214 acres Quadrangie name Blue Ridge Summit MD Qu UTM References do NOT complete UTM references	uadrangle	in Farms Subdivision Quadrangle scale 1:24000
Zone Easting Northing	B Zone	Easting Northing
C	D	
Verbal boundary description and justification Tax Map 13, Parcel 213 Lot 10, Sect	ion 1, Plat 4	and a stop of the
List all states and counties for properties over	lapping state or c	ounty boundaries
state code	county	code
11. Form Prepared By		
name/title Mary Kendall Shipe, Historic	<u>Sites Surveyor</u>	
organization Frederick County Planning &	Zoning Dept. •	late June, 1991
street & number 12 E. Church Street	t	elephone 696-2958
city or town Frederick	s	state MD 21701

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

MARYLAND HISTORICAL TRUST DHCP/DHCD 100 COMMUNITY PLACE **CROWNSVILLE, MD** 21032-2023

301-514-7600

7.1 Description:

The Nevins Log House is located at the intersection of Eyler's Valley Flint Road and Debold Road several miles northwest of Thurmont, Maryland. The principal elevation faces north with a gable roof on a east-west axis. The property includes a large stone springhouse, a bank barn with an attached drive-through shed and a chicken coop.

Constructed circa 1840, the 2 story house of log construction with V-notching rests on a stone foundation. Logs are exposed. The gable roof of standing seam metal has one exterior end stone chimney (new). There is a boxed cornice with cornice returns. Window and door surrounds are plain throughout.

The main (north) elevation has three asymmetrical bays on the first floor with two doors and one 1/1 window. The second floor has two evenly spaced 2/2 windows. Marks in the facade indicate an former full facade porch. The south elevation has three asymmetrical bays on the first floor with one door and two 2/2 windows. The second floor has two evenly spaced 2/2 windows. A two story screened—in porch with a shed roof covers half the elevation. The east and west gable ends are two bays wide. There is new weatherboard in the gables. Windows on symmetrical on both floors with 1/1 windows in the west gable end and 2/2 windows in the east gable end. Each gable end has two 1 light attic windows. There is a basement door in the stone foundation on the east elevation.

An early photograph (circa 1900) shows the house sheathed in weatherboard, having 6/6 windows, two brick interior end chimneys and a one story wrap-around porch. There was also a two story ell extending from the south elevation.

The interior has one large room on the first floor; an original partition was removed. All log ceiling beams and walls throughout the house have been exposed. In the attic, there is an unusual structural feature that survives: a 4 feet tall truss that spreads across part of the attic and projected supports into the floor down to the ground level of the building.

Extensive renovations and alterations have been recently undertaken to fit the tastes of the current owner on both the exterior and interior of the building.

Outbuildings date from the mid-nineteenth century. None of the outbuildings are in use. A large stone springhouse is situated several feet to the east of the house. There is quoining at the corners. A gable roof of corrugated tin and standing seam metal runs east to west. There is a door opening on the west gable end. A door and a window opening on the south elevation have flat wooden lintels.


A large bank barn on a stone foundation sits several yards northwest of the house. It is sheathed in vertical siding and has a gable roof of corrugated tin. A drive-through shed with an arched opening is attached. Four stable openings are in the east elevation. There are small square vent windows throughout the building. A chicken coop, located south of the barn, is sided in weatherboard and has a shed roof with exposed rafters. Ribbons of windows are on the east elevation.


8.1 Significance:

The Nevins Log House is important in showing an original log dwelling house that has been changed to accommodate late twentieth century ideas. These changes have altered the appearance, form and type of building that the nineteenth century owners intended. The outbuildings that accompany the house, no longer in use, exemplify buildings of a mountain farm.

There are many other examples of houses in Frederick County where the log construction material has been exposed. While some log buildings were constructed to be exposed, most of them were sided. Exposing log walls on both the interior and the exterior has become a fashionable trend throughout the county. Unfortunately, it may obscure the integrity of the building as seen in this building, the Nevins Log House.

This farm was owned by Mrs. G. Green in 1858 and A. Bower in 1873. It is located in Eyler Valley and may be connected to the Eyler family who owned farms in the immediate vicinity. The land was probably owned by Eylers at one time.







F-6-84 NEWINS LOS HOUSE 6994 Eylers Valley Flint Road Thurment claimity frederick County
Photo: MARY K SHIDE JUNE 1991 NEC, LOC: MHT North devation + springhouse

1/3



F-6-84 NEWINS LOC HOWE 16994 Eylers Valley Flint Road Frederick County Prote: MARY K SHIPE Tue 1991 NER. CC: MHT Sorth Elevation

,



F-6-84 Nams les Hass 6994 Eylers Valley Flint Road Frederick Country Proto: MARY K SHIPE JNE 1991 NEG LOC: MHT

BARN-looking west